

# Jiangxi Easten Industry Co., Ltd.

Add: New Century 1-2-101, No. 321 Jiefang Road, Nanchang City, Jiangxi Province 330029, P.R. China

Tel: (86) 791-8223089

Fax: (86) 791-8223089

Email: eastenindustry@126.com

Website: www.eastenindustry.com

## Catalogue

### 9. Auto Sensor

#### Odometer Sensor

Picture Item No.	Replace	Picture Item No.	Replace	Picture Item No.	Replace
	<b>PEUGEOT/206</b> 616070		<b>PEUGEOT</b> 6160.24576083A 6PU009161-021		<b>PEUGEOT</b> 6PU009161-031  <b>FIAT</b> 616024  <b>LANCIA</b> 244462683
SR-OM-001		SR-OM-002		SR-OM-003	
	<b>JETTA</b> IH0919149A		<b>VW / AUDI</b> 1H091949C		<b>SUZUKI</b> 26130-64G01 26130-60G11
SR-OM-004		SR-OM-005		SR-OM-006	
	<b>DAEWOO</b> 96213551 SDK050920-09		<b>VW</b> <b>AUDI /A4 /A6</b> 012409191D		<b>HONDA</b> 78410SY0003  <b>TOYOTA</b> 78410-SM4
SR-OM-009		SR-OM-010		SR-OM-011	
	<b>HONDA</b> 7810SV4003 AW78410-SV4		<b>TOYOTA</b> 9187209919		<b>TOYOTA</b> 3802020
SR-OM-012		SR-OM-013		SR-OM-014	

	<b>AUDI / REDFLAG</b> 3802020-JA D12409191D		<b>BORA</b> 232101024 05890161B		<b>AUDI</b> 078905161C
SR-OM-015		SR-OM-016		SR-OM-017	
	<b>VW / BOSCH</b> 06A905161B 06A905161C 232101031		<b>HYUNDAI</b> 96420-4A600		<b>MITSUBISHI</b> 122305.6 WAU2716001
SR-OM-018		SR-OM-019		SR-OM-020	
	<b>PEUGEOT</b>		<b>LADA</b> 3433843		<b>HONDA</b> 8-9710-309-0
SR-OM-021		SR-OM-022		SR-OM-024	
	<b>LADA</b> 3433843		<b>PEUGEOT</b> 90306761		<b>VW</b> 325957827
SR-OM-025		SR-OM-026		SR-OM-028	
	<b>IVECO</b> 282000 4730963		<b>ISUZU</b> 8971188100		<b>DAEWOO</b> 96190708
SR-OM-030		SR-OM-031		SR-OM-032	
	<b>HONDA</b>		<b>JEEP</b> 56027825		3437224035
SR-OM-036		SR-OM-037		SR-OM-039	