

# Jiangxi Eastern Industry Co., Ltd.

Add: New Century 1-2-101, No. 321 Jiefang Road, Nanchang City, Jiangxi Province 330029, P.R. China

Tel: (86) 791-8223089

Fax: (86) 791-8223089






















Email: easternindustry@126.com






















Website: www.eastenindustry.com





















## Catalogue





### I. Ignition Module

Picture Item No.	Replace	Picture Item No.	Replace	Picture Item No.	Replace
	Application: <b>AMERICAN MOTORS</b> JEEP 1992 - 1987 IHC 1975-76	<b>DELCO</b> A1902		Application: JEEP	<b>PRESTOLITE</b> 6566 IDJ3017AS IDJ3017F
	<b>AMC</b> 3224964	<b>ECHLIN</b> TP75		<b>DELCO</b> F1918	<b>TRANPO</b> AM965
IM-001	<b>BWD</b> CBE6	<b>FILKO</b> AL300	<b>IHC</b> 451565C2 DYX193		Application: JEEP 1987-93
	<b>CHRYSLER</b> 3224964	<b>HYBRITEX</b> HAL-1000			<b>BWD</b> CBE39
				<b>ECHLIN</b> TP28	<b>PRESTOLITE</b> 53005079
	<b>IGN MOD BOSCH</b> System: Magnetic Pick-up 6Pin	<b>CARGO</b> 150214		Application: <b>BMW</b> 320, 323i, 630, 633CSI (USA), 722, 728, 733, 735	<b>CARGO</b> 150099
	Application: <b>FORD Escort</b> 1978-89 <b>GM Chevette</b> 1978-89 <b>MONZA 1800cc</b> 1978-89	<b>FORD</b> 324046 324046006 85G12A297		<b>COMMERCIAL IGN.</b> XE123	<b>JA-ELECTRO OY</b> JA-8003
IM-004	<b>BOSCH</b> 9 220 087 005 9 220 087 006	<b>GM</b> 94623323	<b>BOSCH</b> 0 227 100 008 0 227 100 025		Application: <b>VOLKSWAGEN</b> 1991-95
		<b>JA-ELECTRO OY</b> JA-8105	<b>LIGHTEN POINT</b> M21		<b>AUDI / VW</b> 6NO-905-104 867 905 352 867905104A 867905352 6N0905104
					<b>HUCO</b> 13 8419
	Application: <b>Volkswagen</b> 1991- 1993	<b>BOSCH</b> 0 273 200 111 0 273 200 118		Application: <b>AUDI 80 2.0, 1.6</b> <b>MULTIVAN,</b> <b>PASSAT 1.6</b> <b>POLO, VENTO</b>	<b>CEA</b> 587
	<b>AUDI / VW</b> 357 905 352 379 905 352	<b>CARGO</b> 150242		<b>COMMERCIAL IGN.</b> XE140	<b>DURITE</b> 0-350-28
IM-007		<b>CEA</b> 590	<b>BOSCH</b> 1 227 030 030		Application: <b>VW Passat 1.6</b> <b>POLO 1050</b>
		<b>HUCO</b> 13 8417	<b>CARGO</b> 150171		<b>FISTER</b> HW 632
					<b>COMMERCIAL IGN.</b> XE143
					<b>HUCO</b> 13 8008
					<b>INTERMOTOR</b> 15872
	Application: <b>AEG S339109,</b> <b>TZ133876</b> <b>AES 1942</b>	<b>AUTOSTART</b> M105		<b>IGN MOD BOSCH</b> System: Magnetic Pick-up	<b>AUSTIN-ROVER</b> BAU 5332
	<b>AUDI / VW</b> 211 905 351 D 211905351A 211905351B	<b>BERU</b> 0 040 401 002		Application: <b>ALFA ROMEO, BMW, CITROEN, DAIMLER BENZ, PEUGEOT, TALBOT</b>	<b>AUTOSTART</b> M106
IM-010			<b>ALFA ROMEO</b> 116.9765.079.01 705 786	<b>BERU</b> 0 040 401 001 ZM 001	Application: <b>BMW 1979-1984</b> <b>MERCEDES BENZ</b> 1982-1989
				<b>BMW</b> 1214 1266 702	<b>BMW</b> 1214 1287 757 1214 1705 607 1214 1706 439 TSZ-S3371-798812 TSZ53371798812
					<b>CARGO</b> 150163
					<b>COMMERCIAL IGN.</b> XE141
	Application: <b>MERCEDES BENZ</b> 190, 190E 1980-1995	<b>LECLERCQ</b> 030-0090		Application: <b>MERCEDES BENZ</b> 190, 190E 1980- 1995	<b>CARGO</b> 150397
	<b>BOSCH</b> 0 227 100 121 0 227 100 122	<b>MERCEDES-BENZ</b> 002 545 5932		<b>BOSCH</b> 0 227 100 121 0 227 100 122	<b>LECLERCQ</b> 030-0090
IM-013	<b>CARGO</b> 150397	<b>TRANPO</b> BM315		<b>MERCEDES-BENZ</b> 002 545 5932	
				<b>TRANPO</b> BM315	
					Application: <b>LADA VOLVO</b>
					<b>AUTOSTART</b> M108
					<b>COMMERCIAL IGN.</b> XE129
					<b>BOSCH</b> 0 227 100 120
					<b>DODUCO</b> 2004
					<b>CARGO</b> 150074
					<b>DURITE</b> 0-350-22
	<b>IGN MOD BOSCH</b> System: Magnetic Pick-up	<b>KEM</b> E819		<b>AUTOSTART</b> M109	<b>CARGO</b> 150098
	Application: <b>Holden Commodore</b>	<b>LECLERCQ</b> 030-0062		<b>BOSCH</b> 0 227 100 124 1 227 010 003 1 227 010 006	<b>CEA</b> 588
IM-016	<b>BOSCH</b> 9 222 067 021 9-222-067-016 9-222-067-024	<b>MOBILETRON</b> IG-B006H		<b>CITROEN</b> 594551	
		<b>TRANPO</b> BM322			
					Application: <b>CITROEN, FORD, PEUGEOT, RENAULT</b>
					<b>AUTOSTART</b> M110
					<b>BERU</b> 0 040 401 003 ZM 003
					<b>BOSCH</b> 0 227 100 140 1 127 022 017 1 227 022 017 1 227 022 031

 <p>TACH - INPUT - INPUT B1 - B - NC - COIL</p> <p>IM-019</p>	<p><b>AUDI / VW</b> 191 905 351 A 191 905 351 B</p> <p><b>AUTOSTART</b> M111</p> <p><b>BOSCH</b> 0 227 100 142 0 227 100 143</p> <p><b>CARGO</b> 150075</p> <p><b>CEA</b> 583</p>	 <p>INPUT - INPUT B1 - B - B - COIL</p> <p>IM-020</p>	<p><b>AUTOSTART</b> M112</p> <p><b>BOSCH</b> 0 227 100 145</p> <p><b>CARGO</b> 150167</p> <p><b>CEA</b> 580</p> <p><b>COMMERCIAL IGN. XEI37</b></p> <p><b>DODUCO</b> 2002</p> <p><b>DURITE</b> 0-350-21</p>	 <p>INPUTS COIL2 NC B- NC INPUT1 COIL1</p> <p>IM-021</p>	<p><b>ALFA ROMEO</b> 605581530</p> <p><b>BOSCH</b> 0 227 100 201</p> <p><b>FERRARI</b> 137511</p> <p><b>FIAT</b> 7648798 60809477 605581530</p> <p><b>HUCO</b> 13 8401</p> <p><b>IVECO</b> 7648798</p>
 <p>IM-022</p>	<p><b>AES</b> 3043</p> <p><b>BWD</b> CBE14</p> <p><b>CARGO</b> 150029</p> <p><b>CHRYSLER</b> 3 343 850 3 874 020 4 111 850</p> <p><b>DODUCO</b> 2500</p> <p><b>DURITE</b> 0-350-00</p>	 <p>IM-023</p>	<p><b>AES</b> 352</p> <p><b>BWD</b> CBE5</p> <p><b>CHRYSLER</b> 1230938 1230939 3 656 128 3 755 555</p> <p><b>COMMERCIAL IGN. XEI1</b></p> <p><b>ECHLIN</b> TP50</p>	 <p>IM-024</p>	<p><b>IGN MOD DELCO</b> System: Magnetic Pick-up Application: GM, Alfa Romeo, Autobianchi, Ferrari, FSO, Fiat, Lancia, eyland, Peugeot, Renault, Rover, Seat</p> <p><b>AES</b> 298</p> <p><b>AMC</b> 8131941</p> <p><b>AUTOLINK</b> 5-D1906HD</p> <p><b>AUTOSTART</b> M300</p> <p><b>BERU</b> 0 040 401 005 ZM 005</p> <p><b>BORG WARNER</b> CBE4</p>
 <p>IM-025</p>	<p><b>AES</b> 1027</p> <p><b>BWD</b> CBE21</p> <p><b>CARGO</b> 150059</p> <p><b>DELCO</b> 16010090 1894308 1984485 D1918</p> <p><b>DODUCO</b> 2051</p> <p><b>FILKO</b> DR305</p>	 <p>CBA FEDCSA BA</p> <p>IM-026</p>	<p><b>BWD</b> CBE106</p> <p><b>COMMERCIAL IGN. XEI55</b></p> <p><b>DELCO</b> 10467214 D1927A 10499794</p> <p><b>ECHLIN</b> TP406</p> <p><b>FILKO</b> DR318</p> <p><b>MOBILETRON</b> IG-D1927</p>	 <p>IM-027</p>	<p><b>BWD</b> CBE22</p> <p><b>CARGO</b> 150060</p> <p><b>DELCO</b> 16006886 1976239 D1941</p> <p><b>FILKO</b> DR304</p> <p><b>GM</b> 1976 239</p> <p><b>HERTH+BUSS</b> 19 010 010</p>
 <p>IM-028</p>	<p><b>AUTOSTART</b> M301</p> <p><b>BERU</b> 0 040 401 007 ZM 007</p> <p><b>CARGO</b> 150064</p> <p><b>CEA</b> 680</p> <p><b>COMMERCIAL IGN. XEI18</b></p> <p><b>DELCO</b> 7033103</p>	 <p>REF B1 - P1 - P2 REF B2 - P1 - P2</p> <p>IM-029</p>	<p><b>AES</b> 1024</p> <p><b>AUTOSTART</b> M302</p> <p><b>BWD</b> CBE15</p> <p><b>CARGO</b> 150061</p> <p><b>DELCO</b> 1976908 1977907 1978617 1987744 D1948 D1952 D1956 D1963A</p>	 <p>IM-030</p>	<p><b>AES</b> 3182</p> <p><b>AMC</b> 8134117</p> <p><b>AUTOSTART</b> M303</p> <p><b>BERU</b> 0 040 401 006 ZM 006</p> <p><b>BWD</b> CBE17</p> <p><b>CARGO</b> 150062</p>
 <p>IM-031</p>	<p><b>AUTOSTART</b> M620</p> <p><b>CARGO</b> 150063</p> <p><b>COMMERCIAL IGN. XEI38</b></p> <p><b>DELCO</b> 13010892 16010892 1977958 1979107 D1957 D1958 D1961</p>	 <p>REF B1 - P1 - P2 REF B2 - P1 - P2</p> <p>IM-032</p>	<p><b>BORG WARNER</b> CBE26</p> <p><b>CARGO</b> 150239</p> <p><b>DELCO</b> 1987465 D1978 D1979 D1979 10469931 16139369 16140039</p> <p><b>ELITE</b> EI-108</p>	 <p>IM-033</p>	<p><b>BORG WARNER</b> CBE27</p> <p><b>BWD</b> CBE27</p> <p><b>DELCO</b> 16139379 1989747 D1960A D1980</p> <p><b>FILKO</b> DR308</p> <p><b>GUARANTEED PART</b> EL127</p> <p><b>HYBRITEX</b> HDI-1009</p>
 <p>IM-034</p>	<p><b>DELCO</b> D1986A D6134</p> <p><b>TRANSPO</b> DM1986</p>	 <p>REF B1 - P1 - P2 REF B2 - P1 - P2</p> <p>IM-035</p>	<p><b>BORG WARNER</b> CBE28</p> <p><b>ECHLIN</b> TP-25</p> <p><b>ELITE</b> EI-114</p> <p><b>BWD</b> CBE28 CBE38</p> <p><b>DELCO</b> 10496048 D1990 10496269</p>	 <p>IM-036</p>	<p><b>BORG WARNER</b> CBE29</p> <p><b>DELCO</b> 10496541 10496784 D1993</p> <p><b>ELITE</b> EI-115</p> <p><b>FILKO</b> DR313</p> <p><b>HYBRITEX</b> HDI-1011 HDI-1011M</p> <p><b>LECLERCQ</b> 030-0029</p>
 <p>IM-037</p>	<p><b>BWD</b> CBE111</p> <p><b>DELCO</b> 10472184 D1969A 10476631 10487425 D2184</p> <p><b>STANDARD</b> LX-356</p> <p><b>TRANSPO</b> DM2184</p> <p><b>WELLS</b> DR155</p>	 <p>COIL B1 - REF B2 - INPUT - INPUT B</p> <p>IM-038</p>	<p>Application: <b>FORD Fiesta</b> 1974 Orion &amp; Sierra</p> <p><b>AUTOSTART</b> M615</p> <p><b>CARGO</b> 150067</p> <p><b>CEA</b> 885</p> <p><b>COMMERCIAL IGN. XEI11</b></p> <p><b>DODUCO</b> 2253</p> <p><b>DURITE</b> 0-350-10</p> <p><b>FACET</b> 8.7412</p>	 <p>IM-039</p>	<p><b>FORD</b> D4AE-12A199-A1A D4AE-12A199-A1D D4AE-12A199-A2C D4AE-12A199-AA D4AZ-12A199-B</p> <p><b>MOTORCRAFT</b> DY-157B</p> <p><b>TRANSPO</b> FM157</p>

 IM-040	Application: <b>HONDA Accord</b> 94,95 <b>CARGO</b> 150388 <b>HONDA</b> 30120-POA-A01 <b>HUCO</b> 13 8490 <b>ROVER</b> NJW100120 <b>TRANSPO</b> HM311	 IM-041	<b>IGN MOD HITACHI</b> System: Magnetic Pick-up <b>MOBILETRON</b> IG-NS012 <b>NISSAN</b> PRS-IH PRS-1M <b>TRANSPO</b> HM352	 IM-042	Application: <b>HONDA</b> 1993-97 <b>CARGO</b> 150384 <b>HONDA</b> 30130-PO6-006 <b>HUCO</b> 13 8089 <b>LECLERCQ</b> 030-0091 <b>MOBILETRON</b> IG-HD004 <b>TRANSPO</b> HM356
 IM-043	Application: 1992-93 <b>HONDA</b> <b>ACURA</b> 06302-PY3-000 <b>TRANSPO</b> HM363	 IM-044	<b>IGN MOD HITACHI</b> System: Magnetic Pick-up Application: <b>HONDA Prelude</b> 92-94 <b>ACURA</b> 06302-PT2-006 <b>HONDA</b> 06302-PT2-006 <b>TRANSPO</b> HM366	 IM-045	Application: <b>NISSAN</b> 1980-84, 1990-93 <b>FILKO</b> D300 <b>GAP INT. LTD.</b> GP1492 <b>JA-ELECTRO OY</b> JA-NS003 <b>KEM</b> E512 <b>LECLERCQ</b> 030-0057 <b>LIGHTEN POINT</b> M44 <b>LUCAS</b> DAJ 119
 IM-046	Application: <b>NISSAN</b> 1983-86 <b>BWD</b> CBE508 <b>LECLERCQ</b> 030-0095 <b>MOBILETRON</b> IG-NS006 <b>NISSAN</b> 22020-61W00 22020-61W01 22020-61W02 <b>STANDARD</b> LX-556 <b>TRANSPO</b> HM610	 IM-047	Application: <b>NISSAN</b> 1982-84, 1990-96 <b>AES</b> 1879 <b>BORG WARNER</b> CBE509 <b>BWD</b> CBE509 <b>CARGO</b> 150094 <b>ECHLIN</b> TP-108 <b>FILKO</b> D305 <b>GAP INT. LTD.</b> GP1491	 IM-048	Application: <b>NISSAN</b> 1982-84, 1990-96 <b>AES</b> 1880 <b>AUTOSTART</b> M604 <b>BWD</b> CBE503 <b>CARGO</b> 150079 <b>COMMERCIAL</b> <b>IGN.</b> XE115 <b>DODUCO</b> 2350 <b>DURITE</b> 0-350-17
 IM-049	<b>IGN MOD HITACHI</b> System: Magnetic Pick-up Application: <b>NISSAN</b> 1981-86 <b>BWD</b> CBE510 <b>ECHLIN</b> TP116 <b>FILKO</b> D306 <b>JA-ELECTRO OY</b> JA-NS005 <b>KEM</b> E546 <b>LECLERCQ</b> 030-0084 <b>MOBILETRON</b> IG-NS013	 IM-050	<b>AES</b> 1881 <b>AUTOSTART</b> M605 <b>BWD</b> CBE507 <b>CARGO</b> 150091 <b>CEA</b> 686 <b>DODUCO</b> 2300 <b>ECHLIN</b> 9315 1995	 IM-051	<b>BWD</b> CBE561 <b>CARGO</b> 150392 <b>JA-ELECTRO OY</b> JA-8205 <b>LECLERCQ</b> 030-0092 <b>MAZDA</b> E1265 E508-24-910 <b>MOBILETRON</b> IG-NS007
 IM-052	<b>AUTOSTART</b> M200 <b>CARGO</b> 150072 <b>CEA</b> 881 <b>COMMERCIAL</b> <b>IGN.</b> XEI9 XEI33 XEI45 <b>DODUCO</b> 2101 <b>DURITE</b> 0-350-08	 IM-053	<b>IGN MOD LUCAS</b> System: Magnetic Pick-up Application: Austin, Leyland, Rover <b>AUSTIN-ROVER</b> BAU 5100 BAU 5538 <b>AUTOSTART</b> M201 <b>CARGO</b> 150066 <b>CEA</b> 882 <b>COMMERCIAL</b> <b>IGN.</b> XEI12 <b>DODUCO</b> 2100	 IM-054	<b>AUTOSTART</b> M202 <b>CARGO</b> 150175 <b>CEA</b> 880 <b>COMMERCIAL IGN.</b> XEI34 <b>DODUCO</b> 2102 <b>DURITE</b> 0-350-31 <b>FISTER</b> HW 625
 IM-055	Application: <b>JAGUAR</b> 1986-94 <b>BL / JAGUAR</b> DAC10923 DBC5919 DAC7317 DBA5919 <b>LUCAS</b> 54404242 54988204 DAB131 84986 DAB123 DAB136 84985 <b>MOBILETRON</b> IG-D1916	 IM-056	Application: <b>INFINITI</b> 1991-98 <b>NISSAN</b> 1990-98 <b>AUTOSTART</b> M203 <b>CARGO</b> 150221 <b>COMMERCIAL IGN.</b> XEI48 <b>DURITE</b> 0-350-38 <b>HELLA</b> 5DA 006 623-291 <b>HUCO</b> 13 8035 <b>JA-ELECTRO OY</b> JA-8035	 IM-057	<b>CARGO</b> 150222 <b>DURITE</b> 0-350-39 <b>FORD</b> F3XY-12K072-A <b>HUCO</b> 13 8036 <b>JA-ELECTRO OY</b> JA-8036 <b>LECLERCQ</b> 030-0054 <b>LUCAS</b> 84 988
 IM-058	<b>HUCO</b> 13 8086 <b>LUCAS</b> DAB412 <b>MOBILETRON</b> IG-REN02 <b>MOTOROLA</b> 6S 2109 A3J 13-0947 <b>RENAULT</b> 7700860482 <b>TRANSPO</b> LM412	 IM-059	<b>CARGO</b> 150232 <b>HUCO</b> 13 8076 <b>LUCAS</b> 21411918 DAB413 <b>MAGNETI</b> <b>MARELLI</b> 940038580 <b>MOBILETRON</b> IG-REN01 <b>RENAULT</b> 7700 722 070	 IM-060	Application: <b>VOLVO</b> 440, 460 1991-93 <b>CARGO</b> 150237 <b>HUCO</b> 13 8096 <b>LUCAS</b> 21411922 DAB417 <b>MOBILETRON</b> IG-REN03 <b>SIEMENS</b> S10202003B <b>TRANSPO</b> LM417

 <p>IM-061</p>	<p>Application: <b>FORD</b> 1980-85 <b>RELIANT</b> 1985</p> <p><b>AUTOSTART</b> M205</p> <p><b>BERU</b> 0 040 401 008 ZM 008</p> <p><b>BOSCH</b> 1 227 010 014 1 227 022 003</p> <p><b>CARGO</b> 150065 150174</p> <p><b>CEA</b> 585</p>	 <p>IM-062</p>	<p>Application: <b>MAZDA</b> 1986-89</p> <p><b>BWD</b> CBE571</p> <p><b>CARGO</b> 150389</p> <p><b>HUCO</b> 13 8074</p> <p><b>KEM</b> E573</p> <p><b>LECLERCQ</b> 030-0074</p> <p><b>MAZDA</b> B616-18-V60 FEH5-18-V60</p> <p><b>mitsubishi</b> J790X00871</p>	 <p>IM-063</p>	<p><b>BWD</b> CBE538</p> <p><b>CHRYSLER</b> MD112479 MD164475</p> <p><b>GM</b> 96056317 96067829</p> <p><b>HELLA</b> 5DA 006 623-511</p>
 <p>IM-064</p>	<p><b>BWD</b> CBE553</p> <p><b>CARGO</b> 150371</p> <p><b>FORD</b> FOBZ-12A297-A</p> <p><b>HELLA</b> 5DA 006 623-501</p> <p><b>HUCO</b> 13 8470</p> <p><b>JA-ELECTRO OY</b> JA-8204</p> <p><b>MAGNETI MARELLI</b> 940 038 566</p>	 <p>IM-065</p>	<p>Application: <b>MITSUBISHI</b> 1990-92</p> <p><b>CARGO</b> 150378</p> <p><b>HELLA</b> 5DA 006 623-491</p> <p><b>HUCO</b> 13 8452</p> <p><b>LECLERCQ</b> 030-0088</p> <p><b>MITSUBISHI</b> J153 MD618293</p> <p><b>MOBILETRON</b> IG-M010</p>	 <p>IM-066</p>	<p>Application: <b>MAZDA</b> 1989-92</p> <p><b>HELLA</b> 5DA 006 623-481</p> <p><b>HUCO</b> 13 8451</p> <p><b>JA-ELECTRO OY</b> JA-8200</p> <p><b>LECLERCQ</b> 030-0075</p> <p><b>MAGNETI MARELLI</b> 940 038 559</p> <p><b>MAZDA</b> B541-18-V20</p> <p><b>MITSUBISHI</b> J120</p>
 <p>IM-067</p>	<p>Application: <b>MAZDA</b> 1981-85</p> <p><b>HYBRITEX</b> HNI-1004</p> <p><b>KEM</b> E5007</p> <p><b>LECLERCQ</b> 030-0076</p> <p><b>MAZDA</b> E301-24-910</p> <p><b>MITSUBISHI</b> J007X00471 J109</p> <p><b>MOBILETRON</b> IG-M006</p>	 <p>IM-068</p>	<p>IGN MOD MITSUBISHI Application: MAZDA, MERCURY, MITSUBISHI</p> <p><b>FORD</b> F0JY-12A297-C</p> <p><b>LECLERCQ</b> 030-0077</p> <p><b>MAZDA</b> JE01-18-V60</p> <p><b>MITSUBISHI</b> J790X00771 J909 MD611382 MD611539</p> <p><b>MOTORCRAFT</b> DYE-625</p> <p><b>TRANSPRO</b> MM771</p>	 <p>IM-069</p>	<p>IGN MOD MITSUBISHI Magnetic Pick-up Application: <b>FORD</b>, <b>MAZDA</b>, <b>NISSAN</b></p> <p><b>AES</b> 1890</p> <p><b>BOSCH</b> 9-222-067-030</p> <p><b>BWD</b> CBE525</p> <p><b>CARGO</b> 150095</p> <p><b>FILKO</b> D308</p> <p><b>HELLA</b> 5DA 006 623-631</p> <p><b>HUCO</b> 13 8450</p>
 <p>IM-070</p>	<p><b>AUTOSTART</b> M609</p> <p><b>BORG WARNER</b> CBE514</p> <p><b>BWD</b> CBE514</p> <p><b>CARGO</b> 150068</p> <p><b>COMMERCIAL IGN.</b> XEI16</p> <p><b>DODUCO</b> 2310</p>	 <p>IM-071</p>	<p>IGN MOD MITSUBISHI System: Magnetic Pick-up Application: <b>FORD</b> <b>MAZDA</b> 1986-93</p> <p><b>AUTOSTART</b> M623</p> <p><b>BWD</b> CBE517</p> <p><b>CARGO</b> 150160</p> <p><b>ECHLIN</b> 9691</p> <p><b>FORD</b> E9Z212A297A F0Z2-12A297-A F2V7-18-V20</p> <p><b>HELLA</b> 5DA 006 623-421</p>	 <p>IM-072</p>	<p>IGN MOD MITSUBISHI System: Magnetic Pick-up Application: <b>FORD</b> 1988-89</p> <p><b>BWD</b> CBE551</p> <p><b>CARGO</b> 150235</p> <p><b>HUCO</b> 13 8073</p> <p><b>LECLERCQ</b> 030-0089</p> <p><b>MAZDA</b> 8303-18-V20 B303-18-V20</p> <p><b>MITSUBISHI</b> J207</p>
 <p>IM-073</p>	<p>IGN MOD MITSUBISHI System: Magnetic Pick-up Application: <b>MAZDA</b> 1990-94 <b>MERCURY</b> 1991-97</p> <p><b>FORD</b> 19017170 B303-18-V20 E1941 J007X00872 JE15-18-V20</p> <p><b>MAZDA</b> G601-18-V20</p> <p><b>MITSUBISHI</b> J007X00872 J208</p> <p><b>MOBILETRON</b> IG-M012</p>	 <p>IM-074</p>	<p>IGN MOD MITSUBISHI System: Magnetic Pick-up Application: <b>CHRYSLER</b>, <b>DAIHATSU</b>, <b>HYUNDAI</b>, <b>MAZDA</b>, <b>MITSUBISHI</b></p> <p><b>AES</b> 1878</p> <p><b>CARGO</b> 150096</p> <p><b>CHRYSLER</b> MD607814 MD611384</p> <p><b>DODUCO</b> 2312</p> <p><b>ECHLIN</b> 9438 TP-160</p> <p><b>FILKO</b> CH305</p>	 <p>IM-075</p>	<p><b>AUTOSTART</b> M611</p> <p><b>BWD</b> CBE515</p> <p><b>CARGO</b> 150078</p> <p><b>CEA</b> 687</p> <p><b>DODUCO</b> 2311</p> <p><b>DURITE</b> 0-350-16</p> <p><b>ECHLIN</b> TP-162</p>
 <p>IM-076</p>	<p>Application: <b>MITSUBISHI</b> 1991-95</p> <p><b>LECLERCQ</b> 030-0078</p> <p><b>MITSUBISHI</b> J009T03471 J723T J9T03471 MD160535</p> <p><b>MOBILETRON</b> IG-M016</p> <p><b>STANDARD</b> LX-604</p> <p><b>TRANSPRO</b> MM871</p>	 <p>IM-077</p>	<p>IGN MOD <b>NIPPONDENSO</b></p> <p>System: Magnetic Pick-up Application: <b>ACURA</b> 1988-93 <b>HONDA</b> 1988-89</p> <p><b>CARGO</b> 150236</p> <p><b>CEA</b> 692</p> <p><b>COMMERCIAL IGN.</b> XEI44</p> <p><b>DURITE</b> 0-350-43</p> <p><b>ECHLIN</b> 9620</p> <p><b>FISTER</b> HW 640</p> <p><b>HELLA</b> 5DA 006 623-401</p>	 <p>IM-078</p>	<p>Application: <b>HONDA</b> 1991-93</p> <p><b>HONDA</b> 06302-PT3-000</p> <p><b>TRANSPRO</b> NM403</p>
 <p>IM-079</p>	<p>Application: <b>HONDA</b> 1979-87 <b>ROVER</b> 1981-84</p> <p><b>AUSTIN-ROVER</b> BNP 3661 CKP 7061</p> <p><b>AUTOSTART</b> M606</p> <p><b>BWD</b> CBE521</p> <p><b>CARGO</b> 150080</p> <p><b>CEA</b> 688</p> <p><b>COMMERCIAL IGN.</b> XEI13</p>	 <p>IM-080</p>	<p>Application: <b>HONDA PRELUDE</b> 1988-91</p> <p><b>BWD</b> CBE547</p> <p><b>HELLA</b> 5DA 006 623-641</p> <p><b>HONDA</b> 30550-PH3-004</p> <p><b>LECLERCQ</b> 030-0094</p> <p><b>STANDARD</b> LX-638</p> <p><b>TRANSPRO</b> NM405</p>	 <p>IM-081</p>	<p>Application: <b>HONDA</b>, <b>ROVER</b>, <b>STERLING</b></p> <p><b>AUTOSTART</b> M607</p> <p><b>BWD</b> CBE522</p> <p><b>CARGO</b> 150097</p> <p><b>CEA</b> 689</p> <p><b>COMMERCIAL IGN.</b> XEI21</p> <p><b>DODUCO</b> 2302</p> <p><b>ECHLIN</b> 9459</p>

 <p>IM-082</p>	<p>Application: LEXUS SC400 8-Cyl. 1UZFE (Two Dist) 1991-95 CELICA 3SGTE 1992-93 MR2 3SGE (Dist 19100-88364) 1992-94 Pickup 4 Runner 3VZE (Dist 19100-65020) 1992-95 Previa, Van Wagon 2TZFE 1994-95</p> <p><b>NIPPONDENSO</b> 131300-2010 PHD1</p> <p><b>TOYOTA</b> 89621-12050</p> <p><b>TRANSPO</b> NM810</p>	 <p>IM-083</p>	<p><b>MOBILETRON</b> IG-T015</p> <p><b>TOYOTA</b> 89621-26010</p> <p><b>TRANSPO</b> NM815</p>	 <p>IM-084</p>	<p><b>TOYOTA</b> 89621-33020</p> <p><b>TRANSPO</b> NM820</p>
 <p>IM-085</p>	<p>Application: LEXUS LS400, SC400 (4.0L, 2-Reqd) 1995-97 LEXUS LX450 (.5L) 1996-97 TOYOTA 4-Runner (2.7L, -3RZ, -FE) 1996 TOYOTA Camry (2.7L, 5S, -FE) 1992-96 TOYOTA Celica (1.8L, -7A, -FE) 1996-99 TOYOTA Corolla (1.8L, -7A, -FE) 1995-97 TOYOTA Landcruiser (4.5L, -1FZ, -FE) 1993-98 TOYOTA MR2 (2.2L, -5S, -FE) 1992-95 TOYOTA Paseo (1.5L, -5E, -FE) 1992-95 TOYOTA Pickup T100 (2.7L, -3RZ, -FE) 1994-98 TOYOTA Pickup Tacoma (2.4L, -2RZ, -FE) 1995-96 TOYOTA Pickup Tacoma (2.7L, -3RZ, -FE) 1995-96 TOYOTA Previa Supercharged (2.4L, -2TZ, -FZE) 1994-97</p> <p><b>NIPPONDENSO</b> 131300-1740 131300-1744 131300-1950 CHD1</p> <p><b>TOYOTA</b> 89621-16020 89610-26010</p> <p><b>TRANSPO</b> NM825</p>		 <p>IM-086</p>	<p>Application: Lexus ES300, SC300, 3VZE, 2JZGE 1992-95</p> <p><b>NIPPONDENSO</b> 131300-1961 CHD2</p> <p>Camry 3VZE 1991-93</p> <p><b>TOYOTA</b> 89621-33010</p> <p>Supra JZA80, 2JZGE Non-Turbo (Dist 19100-46011) 1993-97</p> <p><b>TRANSPO</b> NM826</p>	
 <p>IM-087</p>	<p>Application: LEXUS LS400 8-Cyl 1UZFE (Two Dist) 1990-93 TOYOTA Celica 3SFE, 3SGELC, 3SGTE, 5SFE (Dist 19100-74050) 1989-91 TOYOTA Landcruiser 3FE 1992, MR2 3FE, 3SGTE (Dist 19100-88363, -74060) 1990-1992 TOYOTA Pickup, 4 runner 3VZE 4X4 1989-91 TOYOTA Previa, Van Wagon 2TZFE (Dist 19100-76010) 1989-93 TOYOTA Tercel 3EE EFI 1989</p> <p><b>NIPPONDENSO</b> 131300-1231 131300-1250</p> <p><b>TOYOTA</b> 89612-12010 89621-30010</p> <p><b>TRANSPO</b> NM827</p>		 <p>IM-088</p>	<p>Application: LADA SAMARA 2108 1500cc</p> <p><b>MOBILETRON</b> IG-H011</p> <p><b>LADA</b> 76.3734 TY37.464.017-89</p> <p><b>TRANSPO</b> RM422</p>	
 <p>IM-089</p>	<p>Application: SKODA 1988-95</p> <p><b>CARGO</b> 150215</p> <p><b>HELLA</b> 5DA 006 623-461</p> <p><b>HUCO</b> 13 8088</p> <p><b>LUCAS</b> DAB 424</p> <p><b>MAGNETI MARELLI</b> TZP443 213 221</p> <p><b>MAGNETON-PAL</b> TZP443 213 221 020</p> <p><b>MOBILETRON</b> IG-SK001</p>	 <p>IM-090</p>	<p><b>IGN MOD LADA</b> System: Hall Effect</p> <p><b>CARGO</b> 150071</p> <p>Application: <b>LADA SAMARA</b> 1.3, 1.5</p> <p><b>CEA</b> 199</p> <p><b>AUTOSTART</b> M612</p> <p><b>BERU</b> 0 040 401 010 ZM 010</p> <p><b>COMMERCIAL</b> IGN. XEI19</p> <p><b>DODUCO</b> 2400</p>	 <p>IM-091</p>	<p><b>AUTOSTART</b> M400</p> <p><b>CARGO</b> 150176</p> <p><b>CEA</b> 381</p> <p><b>COMMERCIAL IGN.</b> XEI30</p> <p><b>DODUCO</b> 2200</p> <p><b>DURITE</b> 0-350-30</p> <p><b>FIAT</b> 9 942 040</p>
 <p>IM-092</p>	<p><b>CARGO</b> 150165</p> <p><b>CEA</b> 182</p> <p><b>DURITE</b> 0-350-32</p> <p><b>HUCO</b> 13 8083</p> <p><b>INTERMOTOR</b> 15030</p> <p><b>JA-ELECTRO OY</b> JA-8555</p> <p><b>LECLERCQ</b> 030-0051</p>	 <p>IM-093</p>	<p><b>AUTOSTART</b> M613</p> <p><b>BERU</b> 0 040 401 009 ZM 009</p> <p><b>CARGO</b> 150088</p> <p><b>CEA</b> 181</p> <p><b>COMMERCIAL</b> IGN. XEI22</p> <p><b>DODUCO</b> 2150</p>	 <p>IM-094</p>	<p><b>MAGNETI MARELLI</b> BKL 3 CA</p> <p><b>MOBILETRON</b> IG-FT003</p> <p><b>TRANSPO</b> XM643</p> <p><b>UNIPONT</b> IM-703</p>